

Windows 10 upgrade by Insure ATM

What are manufacturers saying?

What does Windows 7 end of support mean?

Microsoft will no longer provide security patches, updates or support for the Windows 7 OS.

What are the potential risks of not moving to Windows 10?

- Reputational risk through security vulnerabilities.
- No more security patches i.e. potential exposure to cyber attack.
- Additional upgrade patches will no longer be issued.
- Non-compliance with PCI could result in fines.

What do you need to do?

January 2020 may seem like a long way away, but it isn't. **Connect with Insure ATM now** and together we are able to offer you a cost-effective solution. With this solution you stay in-depended. You are in control of the implementation and time schedule.

Also Insure ATM is in the position to provide **full support** to our global clients and help them realize their deployment goals. Our dedicated and professional Services division is ready to help you, to plan plus implement this upgrade. Windows 10 incorporates optimized security features to the ATM network that are not available in earlier versions.

Together with upgraded security, Windows 10 also brings enhanced interactions to the ATM end-user experience.


WINDOWS 10 SECURITY

Virtualization Based Security **UEFI Secure Boot Device Encryption Device Guard** Credential Guard Windows Trusted Boot Windows Information Protection Microsoft Edge Windows Hello Windows Update BitLocker Admin and Companion Devices Monitoring Windows Defender Trusted Platform Module Windows Firewall Windows Hello BitLocker SmartScreen BitLocker to Go Device Threat Identity Information protection resistance protection protection

LTSC SERVICING


Windows 10 IoT Enterprise

- 10 years of servicing (5 Main + 5 Extended)
- · Security, and required reliability/performance fixes only
- · No feature additions





Three million ATMs around the world run a full version of Windows



NCR PC UPGRADE 58XX / 66XX ESTORIL

ATM Estoril Core Upgrade Solid State Drive Min 500 GB

DVD-RW (SATA)

Parallel Port

PS2 Keyboard Breakout

Extra Serial Ports

8GB Memory

Intel Haswell R i5-4590T

TPM 2.0









